

L Number	Hits	Search Text	DB	Time stamp
-	2	angle near indicator with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:00
-	0	angle near indicator same multimeter and sound near generat\$3 near device	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:05
-	1	angle near indicator same multimeter and sound near generat\$3 near device	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:21
-	2	angle near indicator same multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:21
-	5	angle with indicat\$3 with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:22
-	4	angle with measur\$3 with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:23
-	16	angle with measur\$3 same multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 14:27
-	657	sound same angle same reach\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:43
-	142	sound with angle with reach\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:43
-	4	sound with angle with reach\$3 and torque adj wrench	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:44
-	1	1995-307794.NRAN.	DERWENT	2004/03/22 15:44
-	4	sound with angle with reach\$3 and wrench	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:44
-	11	sound with angle with reach\$3 and torque	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:45
-	3	sound with angle with reach\$3 and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:46
-	0	noise with angle with reach\$3 and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:46
-	0	beep with angle with reach\$3 and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:46
-	0	beep same angle with reach\$3 and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:47
-	3	sound same angle with reach\$3 and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:47

-	249	sound same angle with reach\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:47
-	3	sound same angle same reach\$3 and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/03/22 15:51
-	0	angle with rotation and hous\$4 same shaft same sensor and multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 10:08
-	1443	angle with rotation and hous\$4 same shaft same sensor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 10:09
-	271	angle with rotation and hous\$4 same shaft same sensor and tool	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 11:26
-	48	angle with rotation same hous\$4 same shaft same sensor and tool	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 11:28
-	28	angle with rotation same hous\$4 same shaft same sensor and tool and screw	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 15:10
-	1	5581042.pn.	USPAT; US-PGPUB	2004/10/07 12:20
-	2	angle near indicator with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 15:14
-	2	angle near indicat\$3 with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 15:14
-	3	angle near display with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 15:15
-	5	angle with indicat\$3 with multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 15:15
-	8	angle with indicat\$3 same multimeter	USPAT; US-PGPUB; EPO; JPO; DERWENT	2004/10/07 15:16